

Tree No.	Species	Trunk Caliper
1	Kwanan Cherry	8"
2	Clmson King Norway Maple	7"
3	Amur Cork Tree	12"
4	Norway Maple	18"
5	Honey Locust	16"
60	Norway Maple	10"
61	Norway Maple	13"

**Existing and Potential Root Growth Conflicts**

Minor - Minor upheaval of sidewalk, future worsening of heaving and curb displacement likely due to inadequate tree pit dimensions

Major - Major upheaval of sidewalk, girdled roots, exposed roots, curb displacement, future worsening of heaving and curb displacement likely due to inadequate tree pit dimensions, provides insufficient space for reconstructed curbing

**Overall Tree Health and Conditions**

Fair - Branching conflicts with building and overhead wires, dead branches observed, tree is too large for area

Poor - Branching conflicts with building and overhead wires, center of tree out to accommodate overhead wires, dead branches observed, tree is too large for area

Very Poor - Branching conflicts with building and overhead wires, center of tree out to accommodate overhead wires, large section leaning, growing over roadway posing safety hazard, tree is too large for area

Very Poor - Branching conflicts with building and overhead wires, center of tree out to accommodate overhead wires, large section leaning, growing over roadway posing safety hazard, tree is too large for area

Poor - Branching conflicts with building and overhead wires, health of tree is declining, top has been pruned several times in the past, tree is leaning, growing toward building posing safety hazard, some dead branches observed, canker cavity on at base of tree observed

Fair - Branching conflicts with building and overhead wires, tree is slightly leaning over street, trunk damage observed, large canker cavity at base of tree, weak limb or limb observed, coating higher likelihood of limb breakage or structural failure, tree is becoming too large for area, tree may be near end of normal life cycle

**Existing Tree Legend**  
Recommended Action or Treatment

- REMOVE AND DISPOSE OF EXISTING TREE AND ROOT SYSTEM
- MONITOR EXISTING TREE CONDITIONS - REMOVAL AND DISPOSAL OF TREE AND ROOT SYSTEM LIKELY
- MONITOR EXISTING TREE CONDITIONS - RECOMMENDED ACTION TO BE DETERMINED
- MAINTAIN AND PROTECT EXISTING TREE AND ROOT SYSTEM
- EXISTING TREE LOCATED OUTSIDE OF PROJECT AREA - NO ACTION REQUIRED
- TREE IDENTIFICATION NUMBER FOR INVENTORY

